FactoryProof

PROOF CERTIFICATE

Photo proof certificate

PROOF RECORD ID PR-5T37-AXCB-S282

Verified genuine and unedited since the moment it was taken.



TAKEN
9 Sept 2026, 13:08 CST

WHERE
Lecong, Shunde · 83 m from the factory's registered address

APPROXIMATE COORDINATES
22.97°N, 113.12°E

TAKEN BY
FactoryProof inspector

FACTORY
Lecong Timber Furniture Factory

SHOWS
Dining chair, boucle seat, ash frame (joint close-up)

RECORD SEALED
9 Sept 2026, 13:08 CST

DIGITAL FINGERPRINT

```
76960b5a  fb8dfe82  b74e0c11  b938ebab
e9722bae  e08c036d  9de34d0f  e72326d3
```

An ID-verified FactoryProof inspector took this photo. The moment it was taken, its digital fingerprint, time and location were sealed in a permanent proof record. Anyone can check that record independently, and it can't be changed afterwards.

If you'd like to check it yourself, download the original photo and drop it on the FactoryProof Verify page. Your browser works out the fingerprint, and it should match the one above.

The image shown here is a resized copy, so only the original file will match the fingerprint.

FactoryProof

ISSUED BY FACTORYPROOF

Certificate generated 16 Nov 2026, 14:45 (Sydney time)